

POTABLE WATER SAMPLING FOR LEAD CONCENTRATION SAMPLE COLLECTION FORM 1 of 4

Appendix D

CLIENT INFORMATION

Name:	Enlarged City School District of Troy
Address:	475 First Street Troy NY 12180
Client Rep:	Bob Garland

Date of Sampling:	9/29/2016	4/12/2018
Samples Taken By:	Tim LeVan	Steve Warner
Samples Taken By:		

SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	PS2
BLDG ADDRESS:	470 Tenth Street Troy NY 12180
CONTACT NAME & NUMBERS:	Bob Garland 518-328-5426

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:
1970				

SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information							
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Initial Test Result Lead	Retest Result 2/8/17	Retest lead mg/L result 4/2018	Remediation
1	PS2-01-BF-P-01	Main office bathroom	Sink faucet		1970	X	4:42	4.24			
2	PS2-01-BF-P-02	Boys locker room	Sink faucet		1970	X	4:43	ND			
3	PS2-01-DW1-P-03	Corridor	Water fountain		1970	X	4:44	11.3			
4	PS2-01-DW2-P-04	Corridor	Water fountain		1970	X	Out	of Service	119	0.004	
5	PS2-01-BF-P-05	Girls locker room	Sink faucet		1970	X	Out	of Service	22	0.001	
6	PS2-01-CF-P-06	134 Art	Sink faucet		1970	X	4:47	1.27			
7	PS2-01-CF-P-07	131 Music	Sink faucet		1970	X	4:48	8.94			
8	PS2-01-SF-P-08	Break room	Sink faucet		1970	X	4:51	50.9		0.001	
9	PS2-01-BF1-P-09	Girls room	Sink faucet 1		1970	X	4:52	ND			
10	PS2-01-BF2-P-10	Girls room	Sink faucet 2		1970	X	4:52	ND			
11	PS2-01-BF-P-11	Boys room	Sink faucet		1970	X	4:53	4.63			
12	PS2-01-DW-P-12	Corridor	Water fountain		1970	X	4:53	1.87			
13	PS2-01-SF-P-13	106 Faculty room	Sink faucet		1970	X	4:54	25.3		0.004	
14	PS2-01-CF-P-14	119	Sink faucet		1970	X	4:55	12.5			
15	PS2-01-CF-P-15	107	Sink faucet		1970	X	4:55	10.8			
16	PS2-01-CF-P-16	118	Sink faucet		1970	X	4:56	9.08			
17	PS2-01-BF-P-17	Mens room	Sink faucet		1970	X	4:57	2.62			
18	PS2-01-BF-P-18	Womens room	Sink faucet		1970	X	4:57	ND			
19	PS2-01-CF-P-19	117	Sink faucet		1970	X	4:58	10.1			
20	PS2-01-CF-P-20	Library	Sink faucet		1970	X	5:00	22.1		0.004	
21	PS2-01-CF-P-21	116	Sink faucet		1970	X	5:01	35.9		<0.001	
22	PS2-01-BF1-P-22	Boys room	Sink faucet		1970	X	5:03	0.92			
23	PS2-01-BF2-P-23	Boys room	Sink faucet		1970	X	Out	of Service	ND		
24	PS2-02-BF1-P-24	Boys room	Sink faucet		1970	X	5:05	0.93			
25	PS2-02-BF2-P-25	Boys room	Sink faucet		1970	X	5:05	0.69			

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead (Pb)

Lab:	CNA Environmental St. Peter's Lab Retesting
Contact:	
Comments:	Provide Laboratory Data Report (LDR) and Chain of Custody

CLIENT INFORMATION

Name:	Enlarged City School District of Troy
Address:	475 First Street Troy NY 12180
Client Rep:	Bob Garland

Date of Sampling:	9/29/2016	4/12/2018
Samples Taken By:	Tim LeVan	Steve Warner
Samples Taken By:		

SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	PS2
BLDG ADDRESS:	470 Tenth Street Troy NY 12180
CONTACT NAME & NUMBERS:	Bob Garland 518-328-5426

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:
1970				

SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information							
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Initial Test Results Lead	Retest results 2/8/17	Retest lead mg/L result 4/2018	Remediation
26	PS2-02-CF-P-26	209	Sink faucet		1970	X	5:06	9.47			
27	PS2-02-CF-P-27	206	Sink faucet		1970	X	5:07	9.08			
28	PS2-02-CF-P-28	210	Sink faucet		1970	X	5:08	19.1		<0.001	
29	PS2-02-CF-P-29	205	Sink faucet		1970	X	5:09	17.9		0.002	
30	PS2-02-CF-P-30	211	Sink faucet		1970	X	5:09	15.2		<0.001	
31	PS2-02-CF-P-31	204	Sink faucet		1970	X	5:10	1.12			
32	PS2-02-DW-P-32	Corridor	Water fountain		1970	X	5:11	ND			
33	PS2-02-BF-P-33	Mens room	Sink faucet		1970	X	5:12	1.02			
34	PS2-02-BF-P-34	Womens room	Sink faucet		1970	X	5:12	7.44			
35	PS2-02-CF-P-35	203	Sink faucet		1970	X	5:13	9.49			
36	PS2-02-BF1-P-36	Girls room	Sink faucet 1		1970	X	Out of Service		ND		
37	PS2-02-BF2-P-37	Girls room	Sink faucet 2		1970	X	5:14	0.66			
38	PS2-03-SF-P-38	302 Office	Sink faucet		1970	X	5:15	39.8		<0.001	
39	PS2-03-CF-P-39	304A	Sink faucet		1970	X	5:16	4.5			
40	PS2-03-DW-P-40	Corridor	Water fountain		1970	X	5:18	0.73			
41	PS2-03-CF-P-41	305	Sink faucet		1970	X	5:18	4.27			
42	PS2-03-CF-P-42	306	Sink faucet		1970	X	5:19	9.75			
43	PS2-03-BF1-P-43	Boys room	Sink faucet 1		1970	X	5:20	ND			
44	PS2-03-BF2-P-44	Boys room	Sink faucet 2		1970	X	5:20	0.54			
45	PS2-03-CF-P-45	309	Sink faucet		1970	X	5:21	4.55			
46	PS2-03-CF-P-46	310	Sink faucet		1970	X	5:22	11.5			
47	PS2-03-CF-P-47	311	Sink faucet		1970	X	5:25	13.5			
48	PS2-03-BF-P-48	Mens room	Sink faucet		1970	X	5:25	3.42			
49	PS2-03-BF-P-49	Womens room	Sink faucet		1970	X	5:25	0.87			
50	PS2-03-BF1-P-50	Girls room	Sink faucet 1		1970	X	5:26	0.55			

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

INSTRUCTIONS TO THE LABORATORY - Analyze all samples for both lead (Pb)

Lab:	CNA Environmental St. Peter's Lab Retesting
Contact:	
Comments: Provide Laboratory Data Report (LDR) and Chain of Custody	

CLIENT INFORMATION

Name:	Enlarged City School District of Troy
Address:	475 First Street Troy NY 12180
Client Rep:	Bob Garland

Date of Sampling:	9/29/2016	4/12/2018
Samples Taken By:	Tim LeVan	Steve Warner
Samples Taken By:		

SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	PS2
BLDG ADDRESS:	470 Tenth Street Troy NY 12180
CONTACT NAME & NUMBERS:	Bob Garland 518-328-5426

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:
1970				

SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information							
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Initial Test Result Lead	Retest Result 2/8/17	Retest lead mg/L result 4/2018	Remediation
51	PS2-03-BF2-P-51	Girls room	Sink faucet 2		1970	X	5:26	ND			
52	PS2-03-NS-P-52	318 Nurse	Sink faucet		1970	X	5:30	2.99			
53	PS2-03-NBF-P-53	Nurse Bathroom	Sink faucet		1970	X	5:30	0.62			
54	PS2-03-BF-P-54	Womens room	Sink faucet		1970	X	5:32	7.17			
55	PS2-03-KS1-P-55	Cafeteria serving	Sink faucet 1		1970	X	5:33	1.42			
56	PS2-03-KS2-P-56	Cafeteria serving	Sink faucet 2		1970	X	5:33	2.69			
57	PS2-03-BF-P-57	Mens room	Sink faucet		1970	X	5:33	2.52			
58	PS2-03-DW-P-58	Corridor	Water fountain		1970	X	5:34	ND			
59	PS2-03-CF-P-59	330	Sink faucet		1970	X	5:36	6.88			
60	PS2-03-DW-P-60	330	Water fountain		1970	X	5:36	31.8		0.001	
61	PS2-03-BF-P-61	Womens room	Sink faucet		1970	X	5:37	3.68			
62	PS2-03-BF-P-62	Mens room	Sink faucet		1970	X	5:37	8.24			
63	PS2-03-CF-P-63	333	Sink faucet		1970	X	5:38	2.6			
64	PS2-03-DW-P-64	333	Water fountain		1970	X	5:38	19		0.001	
65	PS2-03-CF-P-65	334	Sink faucet		1970	X	5:41	3.34			
66	PS2-03-DW-P-66	334	Water fountain		1970	X	5:41	34		<0.001	
67	PS2-03-CF-P-67	336	Sink faucet		1970	X	5:44	8.32			
68	PS2-03-DW-P-68	336	Water fountain		1970	X	5:44	14.4			
69	PS2-04-DW-P-69	412 Corridor	Water fountain		1970	X	5:47	1.56			
70	PS2-04-CF-P-70	404	Sink faucet		1970	X	5:47	8.12			
71	PS2-04-DW-P-71	404	Water fountain		1970	X	5:47	49.4		0.001	
72	PS2-04-CF-P-72	407	Sink faucet		1970	X	5:50	8.49			
73	PS2-04-DW-P-73	407	Water fountain		1970	X	5:50	29		0.011	
74	PS2-04-CF-P-74	408	Sink faucet		1970	X	5:54	2.68			
75	PS2-04-DW-P-75	408	Water fountain		1970	X	5:54	10.9			

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead (Pb)

Lab:	CNA Environmental St. Peter's Lab Retesting
Contact:	
Comments: Provide Laboratory Data Report (LDR) and Chain of Custody	

